


SAFETYFLYER

Safety Alert Dynamic Positioning

2023-09 Alert DP Switch over

Recently two DP occasions have occurred within the SNS Pool where one led to a collision platform due to instable DP model



- + We like to point out the importance of the DP operators and the actions they take. There is always time to do it right.
- + Fill the checklist correctly and give the system time to build up a model.

+ In case of doubt remain outside the safety zone and inform SNSPool management accordingly.

+ Always think twice before you make a decision



- Never enter a safety zone of an offshore location without a proper DP model.
- Always take time to fill the DP checklist and test your systems
- Stand clear in case of doubt